Regency
the first name in solid state

PROFESSIONAL
2 WAY action radio

DATE 7/7/82

SSC Service Bulletin

no. 82-258

TO: REGENCY COMMUNICATIONS PROFESSIONAL SALES & SERVICE CENTERS

REGENCY COMMUNICATIONS PROFESSIONAL SALES REPRESENTATIVES

MODELS AFFECTED: MCH40, MCL 60 SERIES, MCBH45, MCCH06, MCCH09

SYMPTOM: POLARITY OF ELECTROLYTIC CAPACITOR IN THE AUDIO AMP. IS REVERSED RESULTING IN POSSIBILITY OF LOW OR DISTORTED AUDIO

CURE:

Install new capacitor (Part #1513-0221-002) with positive side towards IC202, Pin 2.

For MCH40 boards (704-051, 704-011), the capacitor is C245.
For MCL60 board (704-111) the capacitor is C238.

Models built after July, 1982 have this error corrected.

TECHNICAL SERVICE DEPARTMENT
REGENCY COMMUNICATIONS, INC.